www.himedialabs.com Safety data sheet(SDS) According to Regulation (EC) No.1907/2006 Revision : 00000 Date of Revision : 19/06/2017 1 Identification of the substances/ mixture and of the company/ undertaking 1.1 **Product Identifiers** Product Number FD150 Product Name NYC Supplement REACH Registration Number This product is a mixture. Reach registration number is not available for this mixture. Relevant identified uses of the substance or mixture and uses advised against 1.2 1.2.1 Relevant identified uses Laboratory Chemicals, Analytical Purpose, Biochemical Analysis For InVitro Diagnostic Use Details of the supplier of the safety data sheet 1.3 Produced by HiMedia Laboratories Private Limited Address 23, Vadhani Industrial Estate, LBS Marg, Ghatkopar (W), Mumbai - 400 086 India Tel. No. +91-22-2500 0970, +91-22-2500 1607 Fax No. : +91-22-25002468 Mail Id info@himedialabs.com Website : www.himedialabs.com 1.4 **Emergency Tel. No.** Emergency Tel. No. Please contact the regional HiMedia representation in your country

2 Hazards Identification

2.1 Classification of the substance or mixture *CLP Classification-Regulation (EC) No. 1272/2008[EU-GHS/CLP]*

Sensitisation, Skin, (Category 1), H317

2.2 Label elements Labeling according to Regulation (EC) No.1272/2008



Pictogram Signal word Warning

Hazard Statement(s)

H317 May cause an allergic skin reaction

Precautionary Statement(s)

- P261 Avoid breathing dust/fume/gas/mist/vapours/spray.
- P333 + P313 IF SKIN irritation or rash occurs: Get medical advice/attention.
- P280 Wear protective gloves/protective clothing/eye protection/face protection.
- P302 + P352 IF ON SKIN: wash with plenty of soap and water.

2.3 Other Hazards

None

Page **1** of **7**

3 Composition/Information On Ingredients

3.2 Mixture

	Co	mponent	Classification	Concentration			
	Vancomycin hy						
	CAS No. :	1404-93-9	As Per EC Regulation 1272/2008 Skin Sens. 1 H317	>=10 - <=20%			
	Refer Section 16	o for complete statem	ent of H codes and its classification				
Ļ	First Aid Measu	ires					
4.1	Description of first aid measures						
	General advice						
	Consult a physician. Show this safety data sheet to the doctor in attendance.						
	If inhaled						
	If breathed in, move person into fresh air. If not breathing, give artificial respiration. Consult a physician.						
	In case of skin contact						
	Wash with plenty of soap and water. Consult a physician.						
	In case of eye contact						
	Rinse immediately with plenty of water for at least 15 minutes. Consult a physician.						
	If swallowed						
	Never give anything by mouth to an unconscious person. Rinse mouth with water. Consult a physician.						
4.2	Most important symptoms and effects, both acute and delayed No data available.						
4.3	Indication of im No data availab		ention and special treatment needed				
5	Fire Fighting Me	easures					
5.1	Extinguishing media						
	Suitable extinguishing media						
	Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide.						
	Unsuitable extinguishing media						
	No data available.						
5.2		arising from the subs					
		nposition products no	ot known.				
5.3	Precautions for	-	tue for fire fighting if recorder .				
E /	Further information of the self contains the sel		atus for fire fighting if necessary				
5.4	No data availab						
	No data avallabi	le					

 Accidental Release Measures Personal procetution. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. Methods and materials for containment and cleaning up Soak up with inert absorbent material. Keep in suitable, closed containers for disposal. Reference to other sections For disposal see Section 13. Handling and Storage Precentive fire protection. Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. <i>Recommended Storage Temperature : On receipt store between 2-8°C</i> Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. Exposure Controls/Personal Protection Components with workplace control parameters Exposure controls Apropriote engineering controls Appropriote engineering controls Aport protection Tightly fitting saftey goggles; faceshield (8-inch minimum). Use equipment for eye protection tested and approved under approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Tightly fitting saftey goggles; faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Tightly fitting saftey goggles; faceshield for to use. Use proper glove removal technique (without ouching glove's outer surface) to avoid skin contact with his						
 Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. Convionmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. Methods and materials for containment and cleaning up Soak up with inert absorbent material. Keep in suitable, closed containers for disposal. Reference to other sections For disposal see Section 13. Handling and Storage Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for preventive fire protection. Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. <i>Recommended Storage Temperature :</i> On receipt store between 2-8°C Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. Exposure Controls/Personal Protection Store in controls are specific uses are stipulated. Exposure controls Appropriate engineering contains. Wash hands before breaks and immediately after handling the products. Personal protective equipment Hygien measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. EVE/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with gloves. Gl	6	Accidental Release Measures				
 Evacuate personnel to safe areas. Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. Methods and materials for containment and cleaning up Soak up with inert absorbent material. Keep in suitable, closed containers for disposal. Reference to other sections For disposal see Section 13. Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for preventive fire protection. Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opend must be carefully resealed and kept upright to prevent leakage. Recommended Storage Temperature : On receipt store between 2-8°C Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. Exposure Controls/Personal Protection Store to with workplace control parameters Components with workplace control parameters Apart from the uses mentioned in section 1.2 no other specific uses and immediately after handling the products. Personal protection Appropriate engineering controls Appropriate engineering context Appropriate engineering contex	6.1					
 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert absorbent material. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for preventive fire protection. 7.2 Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. Recommended Storage Temperature : On receipt store between 2-8°C 7.3 Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. 8 Exposure Controls/Personal Protection 8.1 Control parameters Components with workplace control parameters 8.2 Exposure controls Appropriate engineering controls approventive skin protection. Wash hands and face after working with the product. Eye/foce protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166						
 Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with iner absorbent material. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for preventive fire protection. 7.2 Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. Recommended Storage Temperature : On receipt store between 2-8°C 7.3 Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. 8 Exposure Controls/Personal Protection 8.1 Control parameters Components with workplace control parameters 8.2 Exposure controls Appropriate engineering controls Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. Personal protective equipment Hygiene measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. Eye/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Disp		·				
 6.3 Methods and materials for containment and cleaning up Soak up with inert absorbent material. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for preventive fire protection. 7.2 Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. <i>Recommended Storage Temperature</i> : On receipt store between 2-8°C 7.3 Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. 8 Exposure Controls/Personal Protection 8.1 Control parameters Components with workplace control parameters 8.2 Exposure controls Appropriate engineering controls Appropriate engineering Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's souter surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective g	6.2	•				
 Soak up with inert absorbent material. Keep in suitable, closed containers for disposal. Reference to other sections For disposal see Section 13. Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for preventive fire protection. Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. Recommended Storage Temperature : On receipt store between 2-8°C Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. Exposure Controls/Personal Protection Components with workplace control parameters Components with workplace control parameters Exposure contols Appropriate engineering controls Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. Personal protective equipment Hygiene measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. Eye/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approval under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective form it. Body protection Complete suit protection against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 						
 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for preventive fire protection. 7.2 Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. <i>Recommended Storage Temperature :</i> On receipt store between 2-8°C 7.3 Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. 8 Exposure Controls/Personal Protection 8.1 Control parameters Components with workplace control parameters 8.2 Exposure Controls/ Appropriate engineering controls Appropriate engineering controls Appropriate engineering controls Appropriate engineering controls Appropriate engineering controls May and the products. Personal protective equipment Hygiene measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. Eye/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dan	6.3					
 For disposal see Section 13. 7 Handling and Storage 7 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for preventive fire protection. 7.2 Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. Recommended Storage Temperature : On receipt store between 2-8°C 7.3 Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. 8 Exposure Controls/Personal Protection S.1 Control parameters Components with workplace control parameters Components with workplace control parameters Components with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. Personal protective equipment Hygiene measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. Eye/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive By/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against che						
 7 Handling and Storage 7. Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for preventive fire protection. 7.2 Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. <i>Recommended Storage Temperature</i> : On receipt store between 2-8°C 7.3 Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. 8 Exposure Controls/Personal Protection 8.1 Control parameters Components with workplace control parameters 8.2 Exposure controls Appropriate engineering controls Appropriate engineering controls Appropriate engineering controls Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. <i>Personal protective equipment</i> <i>Hygiene measure</i> Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. <i>Eye/face protection</i> Tightly fitting saftery gogles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected accord	6.4					
 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for preventive fire protection. Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. <i>Recommended Storage Temperature</i> : On receipt store between 2-8°C Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. Seconserved and the uses mentioned in section 1.2 no other specific uses are stipulated. Seconserved controls/Personal Protection Source Controls/Personal Protection Seconserved controls and the products. Personal protective equipment Hygiene measure Immediately change controls Appropriate engineering controls Appropriate engineering controls Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. Personal protective equipment Hygiene measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. Eye/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Body protection Component against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific wo		For disposal see Section 13.				
 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for preventive fire protection. Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. <i>Recommended Storage Temperature</i> : On receipt store between 2-8°C Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. Seconserved and the uses mentioned in section 1.2 no other specific uses are stipulated. Seconserved controls/Personal Protection Source Controls/Personal Protection Seconserved controls and the products. Personal protective equipment Hygiene measure Immediately change controls Appropriate engineering controls Appropriate engineering controls Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. Personal protective equipment Hygiene measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. Eye/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Body protection Component against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific wo	_					
 Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for preventive fire protection. 7.2 Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. <i>Recommended Storage Temperature :</i> On receipt store between 2-8°C 7.3 Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. 8 Exposure Controls/Personal Protection 8.1 Control parameters Components with workplace control parameters 8.2 Exposure controls Appropriate engineering controls Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. <i>Personal protective equipment</i> <i>Hygiene measure</i> Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. <i>Eye/face protection</i> Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good alboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. <i>Body protection</i> Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific						
 preventive fire protection. 7.2 Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. <i>Recommended Storage Temperature :</i> On receipt store between 2-8°C 7.3 Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. 8 Exposure Controls/Personal Protection 8.1 Control parameters Components with workplace control parameters 8.2 Exposure controls <i>Appropriate engineering controls</i> Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. <i>Personal protective equipment Hygiene measure</i> Immediately contage to contained clothing. Apply preventive skin protection. Wash hands and face after working with the product. <i>Eye/face protection</i> Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive <i>By/SB6/EEC</i> and the standard EN 374 derived from it. <i>Body protection</i> Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace.	7.1					
 Conditions for safe storage, including any incompatibilities Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. <i>Recommended Storage Temperature :</i> On receipt store between 2-8°C Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. Exposure Controls/Personal Protection Control parameters Components with workplace control parameters Components with workplace control parameters Aport from the uses and clothing. Wash hands before breaks and immediately after handling the products. <i>Personal protective equipment Hygiene measure</i> Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. <i>Eye/face protection</i> Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. <i>Byelf</i>(SEC and the standard EN 374 derived from it. <i>Body protection</i> Componer gloves face use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive <i>BylogEEC</i> and the standard EN 374 derived from it. <i>Body protection</i> Componets with protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. Asset and the						
 Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. <i>Recommended Storage Temperature :</i> On receipt store between 2-8°C 7.3 Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. 8 Exposure Controls/Personal Protection 8.1 Control parameters Components with workplace control parameters 8.2 Exposure controls <i>Appropriate engineering controls</i> Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. <i>Personal protective equipment</i> <i>Hygiene measure</i> Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. <i>Eyeface protection</i> Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. <i>Body protection</i> Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 						
 are opened must be carefully resealed and kept upright to prevent leakage. Recommended Storage Temperature : On receipt store between 2-8°C 7.3 Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. 8 Exposure Controls/Personal Protection 8.1 Control parameters Components with workplace control parameters 8.2 Exposure controls Appropriate engineering controls Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. Personal protective equipment Hygiene measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. Eyeface protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves'after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace.	1.2					
 Recommended Storage Temperature : On receipt store between 2-8°C Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. Exposure Controls/Personal Protection Components with workplace control parameters Components with workplace control parameters Components with workplace control parameters Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. Personal protective equipment Hygiene measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. Eye/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 						
 7.3 Specific end uses Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. 8 Exposure Controls/Personal Protection 8.1 Control parameters Components with workplace control parameters 8.2 Exposure controls Appropriate engineering controls Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. Personal protective equipment Hygiene measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. Eye/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 						
 Apart from the uses mentioned in section 1.2 no other specific uses are stipulated. 8 Exposure Controls/Personal Protection 8.1 Control parameters Components with workplace control parameters 8.2 Exposure controls Appropriate engineering controls Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. Personal protective equipment Hygiene measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. Eye/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 	7 3					
 8 Exposure Controls/Personal Protection 8.1 Control parameters Components with workplace control parameters 8.2 Exposure controls <i>Appropriate engineering controls</i> Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. <i>Personal protective equipment Hygiene measure</i> Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. <i>Eye/face protection</i> Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. <i>Body protection</i> Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 	7.5	•				
 8.1 Control parameters Components with workplace control parameters 8.2 Exposure controls Appropriate engineering controls Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. Personal protective equipment Hygiene measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. Eye/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 		Apart nom the uses mentioned in section 1.2 no other specific uses are supulated.				
Components with workplace control parameters8.2Exposure controlsAppropriate engineering controlsAvoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products.Personal protective equipment Hygiene measureImmediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product.Eye/face protectionTightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU).Skin protectionHandle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it.Body protectionComplete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace.	8	Exposure Controls/Personal Protection				
 8.2 Exposure controls Appropriate engineering controls Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. Personal protective equipment Hygiene measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. Eye/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace.	8.1	Control parameters				
Appropriate engineering controlsAvoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products.Personal protective equipmentHygiene measureImmediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product.Eye/face protectionTightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU).Skin protectionHandle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices.Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it.Body protectionComplete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace.		Components with workplace control parameters				
 Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products. <i>Personal protective equipment</i> <i>Hygiene measure</i> Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. <i>Eye/face protection</i> Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. <i>Body protection</i> Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 	8.2	Exposure controls				
 handling the products. Personal protective equipment Hygiene measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. Eye/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 		Appropriate engineering controls				
Personal protective equipmentHygiene measureImmediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product.Eye/face protectionTightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU).Skin protectionHandle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices.Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it.Body protectionComplete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace.						
 Hygiene measure Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. Eye/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 						
 Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product. <i>Eye/face protection</i> Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. <i>Body protection</i> Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 						
 after working with the product. <i>Eye/face protection</i> Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. <i>Body protection</i> Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 						
 Eye/face protection Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). Skin protection Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 						
 Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. <i>Body protection</i> Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 						
and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU). <i>Skin protection</i> Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. <i>Body protection</i> Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace.						
 Skin protection Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 						
 Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 						
 (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace. 		•				
contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace.						
Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace.						
89/686/EEC and the standard EN 374 derived from it. Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace.						
Body protection Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace.						
Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace.						
according to the concentration and amount of the dangerous substance at the specific workplace.						
κεεριτατοι γ ριοτευτιστ						
		πεεριτατοιγ μιστευτιστ				

Where risk assessment shows air-purifying respirators are appropriate use a full-face respirator with multi-purpose combination (US) or type ABEK (EN 14387) respirator cartridges as a backup to engineering controls. If the respirator is the sole means of protection, use a full-face supplied air respirator. Use respirators and components tested and approved under appropriate government standards such as NIOSH (US) or CEN (EU).

Environment exposure controls

Do not empty into drains.

9 Physical and chemical properties

9.1 Information on basic physical and chemical properties

Yellow powder
No data available

9.2 Other safety information

No data available

10 Stability and Reactivity

10.1 Reactivity No data available

- **10.2 Chemical stability** No data available
- **10.3 Possibility of hazardous reactions** No data available
- **10.4** Conditions to avoid No data available
- **10.5** Incompatible materials No data available
- **10.6 Hazardous decomposition products** Other Decomposition products not known.

Page 4 of 7

11 Toxicological Information

11.1 Information on toxicological effects

Acute toxicity No data available Skin corrosion/irritation No data available Serious eye damage/eye irritation No data available Respiratory or skin sensitisation Mixture may cause skin sensitisation.

Carcinogenicity

IARC: No component of this product present at levels greater than or equal to 0.1% is identified as probable, possible or confirmed human carcinogen by IARC.

Specific target organ toxicity- single exposure

No data available Specific target organ toxicity - repeated exposure No data available Aspiration hazard No data available **Potential Health Effects** Inhalation **REFER SECTION 2** Skin **REFER SECTION 2** Eves **REFER SECTION 2** Ingestion **REFER SECTION 2** Additional Information **RTECS** : Not Available

11.2 Components

Vancomycin Hydrochloride Acute Oral Toxicity Rat LD50: 10,000 mg/kg Mouse LD50: 5,000 mg/kg Acute Intraperitoneal Toxicity Rat LD50:2218 mg/kg Mouse LD50:1734 mg/kg Acute Intravenous Toxicity Rat LD50: 319 mg/kg Acute Subcutaneous Toxicity Mouse LD50: >5000mg/kg

Adiitional information:

RTECS: YW4380000

12 **Ecological Information**

12.1 Toxicity

No data available

12.2 Persistence and degradability No data available

- 12.3 **Bioaccumulative potential** No data available
- 12.4 Mobility in soil No data available
- 12.5 PBT and vPvB assessment PBT/vPvB assessment was not conducted as chemical safety assessment is not required.
- 12.6 Other adverse effects No data available

13 **Disposal Considerations**

13.1 Waste treatments methods Product

Offer surplus and non-recyclable solutions to a licenced disposal company. Contact a licenced professional waste disposal service to dispose off this material.

13.2 **Contaminated packaging** Dispose of as unused product.

14 **Transport Information**

14.1 UN-No

ADNR : ADR : IATA_C : IATA_P : IMDG : RID :

UN proper shipping name 14.2

- ADNR : Not dangerous goods
- ADR : Not dangerous goods
- : Not dangerous goods
- IATA_C IATA_P : Not dangerous goods
- IMDG : Not dangerous goods
- RID : Not dangerous goods

14.3 Transport hazard class(es)

ADNR : - ADR : - IATA_C : - IATA_P : - IMDG : - RID : -

14.4	Packaging group ADNR : ADR : IATA_C : IATA_P : IMDG : RID :				
14.5	Environmental hazards ADNR : No ADR : No IMDG : Marine pollutant No IATA_C : No IATA_P : No RID : No				
14.6	Special precautions for use No data available				
15	Regulatory Information This safety datasheet complies with the requirements of Regulation(EC) No. 1907/2006.				
15.1	Safety health and environment regulations/legislation specific for the substance or mixture				
15.2	No data available Chemical Safety Assessment No data available				
16	Other information				
	Text of H codes and classification mentioned in section 3				
	H317 May cause an allergic skin reaction				
	Skin Sens. 1 Sensitisation, Skin, Category 1				
	Further Information				

Copyright 2017 HiMedia Laboratories Pvt. Ltd.

The information given in this safety data sheet is believed to be correct yet does not claim to be all inclusive. This document is intended only as a guide for appropriate precautionary handling of the material by properly trained individuals, information here being commensurate with the present state of our knowledge regarding the manner and conditions of use, handling, storage or disposal. The information provided herein shall not be considered as guarantee of the properties of the product. HiMedia Laboratories, shall not be held liable for any damage resulting from improper handling or contact with the above product. Unless explicitly stated on the product or in any of the documentation accompanying the product, it is intended for research or testing purpose only and is not to be used for any other purpose.